

Reliability

Fluke 3563 Analysis Vibration Sensor


Frequently asked questions



1	ſ	1		1
ų	L.	_	1	
			5	

Why should I use a vibration sensor, and what is the benefit?	 Wibration anomalies are some of the first indications of misalignment, looseness, bearing wear, or imbalance faults within mechanical rotating equipment. By continuously monitoring assets, maintenance and reliability teams can better understand when maintenance repairs and replacement should be completed. Wireless sensors overcome the challenges faced by maintenance teams in all industries: limited time, resources, and access to machines (i.e., those behind panels, in high places, in hazardous areas, etc.). You can: Determine the fault causing a problem and decide critical 	
	next-step actions.	
	• Repair machines before failures occur to increase production revenue and lower energy waste and maintenance costs.	
What are the key features of the Fluke 3563 Analysis Vibration Sensor?	A : The 3563 features include a unique floating, piezoelectric sensor and:	
	• Smart battery management capability with a user-determined data transmission rate.	
	 Users can configure the sensor based on machine type for precise readings without manually entering severity thresholds. 	
	 Powerful analysis capabilities of LIVE-Asset[™] Portal software to analyze both banded overall values and narrowband values. 	
	 Wireless gateway possesses dual network connection capabilities—Wi-Fi and Ethernet—so your system can fit your facility. 	









Q: How does the sensor work to measure Overall Vibration and time waveform?	The digitized vibration measurements are processed either as overall values or as raw data. The gateway can be triggered from the cloud-based Data Platform to instruct the sensor to record a time waveform signal. This raw signal is then transferred via the gateway and back to the Data Platform. Another portion of the raw signal is converted to overall values and compared with the overall threshold values. If the threshold values are exceeded, an alarm signal is sent to the gateway. The gateway will then send a request to the sensor to transfer the overall values, causing the alarm signal. If there is no alarm signal, the overall values are saved.
Q: What is the Fluke 3503 Wireless Gateway, and how does it work?	A: The system gateway is the central bridge between a 3563 Analysis Vibration Sensor and the Accelix [™] cloud-based data platform.
FLUKE 3503 Wireless Gateway	The gateway collects measurement data from the sensors and transfers the data to Accelix. A single gateway communicates with up to 20 sensors.
	The gateway uses a low-energy wireless protocol to communicate with the sensor. Communication between the gateway and Accelix is based on IoT technology (MQTT) and is bidirectional. The measurement data collected by the sensor is processed in Accelix.
	To save energy, the low-energy wireless protocol connection between the sensor and the gateway is established on-demand only, except for alarm signals that are generated if specified thresholds are exceeded. In case of an alarm, the gateway requests the sensor's measured overall values and sends them to Accelix. At the same time, Accelix triggers the gateway to request the sensor to measure a time waveform signal (TWF).
	NOTE: The TWF signal is never stored on the sensor but measured anew when requested by Accelix. Before any vibration or temperature measurements may be taken, the gateway must be configured. The configuration of
	the gateway and the measuring sensor takes place in the LIVE-Asset Portal.
Q: What are the frequency, communication, and interval from the sensor to the	Frequency: 2.4 GHz ISM band according to IEEE 802.15.1
gateway?	 Sensor-to-Gateway communication range: Up to 100m line-of-sight, depending on environment
	• Transmission Interval: Configurable, minimum default is every 10 minutes











e sensor with a smooth, even mounting d sensor installation method is to screw r into the measurement location. If screw		
As most test surfaces are curved, the sensor uses a mounting adapter to provide the sensor with a smooth, even mounting surface. The preferred sensor installation method is to screw the mounting adapter into the measurement location. If screw mounting is not possible or not allowed, attach the adapter to the measurement location using an adhesive. Image: Comparison of the measurement location of the measurement location using an adhesive. Image: Comparison of the measurement location using an adhesive. Image: Comparison of the measurement location using an adhesive. Image: Comparison of the measurement location using an adhesive. Image: Comparison of the measurement location using an adhesive. Image: Comparison of the measurement location using an adhesive. Image: Comparison of the measurement location using an adhesive of the measurement location using an adhesive mount location using an adhesive mount location. Image: Comparison of the measurement location using an adhesive mount location. Image: Comparison of the measurement location using an adhesive mount location. Image: Comparison of the measurement location. Image: Comparison of the measurement location using a mathematic dathesive mount location. Image: Comparison of the measurement location. Image: Comparison of the measurement location using a mathematic dathesive mount location. Image: Comparison of the measurement location. Image: Comparison of the measurement location. Image: Comparison of the measurement location. Image: Comparison of the measurement location. Image: Comparison of the		
With the adhesive well applied on the three magnets and the center disc, the sensor is pressed to the mounting adapter to form a firm permanent bond. Once bonded, the mounting adapter now becomes part of the sensor. (The sensor CANNOT be removed from the adapter.)		
ccur if a sensor is moved from the or could damage the sensor internals are not good troubleshooting tools (use		
and is replaced? If I am careful, can I move eries or move the sensor to a new place, g adapter must be unscrewed from the ion.		
anting adapter is used, the adhesive's bond carefully turning the adapter with the adapter wrench. Once the adapter and free from the machine surface, remove any rom the adapter surface using a grinding		

Fluke Corporation PO Box 9090, Everett, WA 98206 U.S.A.

For more information call: In the U.S.A. 856-810-2700 In Europe +353 507 9741 In UK +44 117 205 0408 Email: cumper/fuences/ir.com Email: support@accelix.com Web access: flukereliability.com

@2021 Fluke Corporation. Specifications subject to change without notice. 06/21/2021 $6013903d\mbox{-en}$

Modification of this document is not permitted without written permission from Fluke Corporation.